
SWITZERLAND

Phone: +41 (0) 43 931 61 68

Telegraphic address:

AFTN LSSAYOYX

Email: aip@skyguide.ch



AIP Services
P.O. Box
CH-8602 Wangen bei Dübendorf
Switzerland

Non-AIRAC AIP SUP: 002/2021

Effective Date: 07-OCT-2021

End Date: 27-JAN-2022

Publication Date: 07-OCT-2021

Maintenance Check Flights and Test Flights within LSAG CTA

General

For better management of ACC workload, the following coordination procedure is defined for aircraft operators planning maintenance check flights and test flights within LSAG CTA.

Coordination procedure

Maintenance check flights and test flights within airspace class C and D are subject to coordination with skyguide as defined in AIP Switzerland (ENR 1.4 § 2).

If the 10 working days prior notification required in the process cannot be met, the following announcement procedure may be used exceptionally for flights within LSAG CTA.

- At least 6 hours before the flight, aircraft operators shall provide all relevant information about the conduct of the flight to Geneva ACC SPVR by phone (+41 22 417 40 40).
- 1 hour before the flight, aircraft operators shall contact Geneva ACC SPVR by phone again (+41 22 417 40 40) to confirm the flight program.

THIS PAGE INTENTIONALLY LEFT BLANK